# Scientific Research

# Growth Kinetics of Nd<sub>2</sub>Fe<sub>14</sub>B Phase During Hydrogen-Induced Reverse Phase Transformation in Nd<sub>2</sub>Fe<sub>14</sub>B Type Nanocrystalline Magnetic Alloy

#### Sergey Borisovich Rybalka

Department of Physics, Donetsk National Technical University, Donetsk, Russia Email: rybalka@rambler.ru

Received January 13th, 2011; revised March 17th, 2011; accepted June 17th, 2011

## ABSTRACT

The influence of hydrogen pressure on kinetics of growth of  $Nd_2Fe_{14}B$  phase during hydrogen-induced reverse phase transformations in the industrial  $Nd_2Fe_{14}B$  hard magnetic alloy has been studied. It has been determined that, as the temperature and the initial hydrogen pressure increase, a reverse phase transformation significantly accelerates. It has been shown that the kinetics of the reverse phase transformation is controlled by the Fe atoms diffusion and that the rate growth of new  $Nd_2Fe_{14}B$  phase increase with increase of initial hydrogen pressure. On the base of the Kolmogorov kinetic theory the kinetic equation describing influence of initial hydrogen pressure on the isothermal kinetic diagram for this transformation has been obtained.

Keywords: Intermetallics, Growth Kinetics, Permanent Magnets, Gas-solid Reactions

#### 1. Introduction

As well known permanent magnet materials of a RE-TM (rare-earth-transition-metal) type are key components of numerous modern devices [1]. There are many processing routes for improving of their magnetic properties [2]. In particular, one from perspective technologies for improvement of magnetic properties of RE-TM type alloys is HDDR-process (Hydrogenation-Decomposition-Desorption-Recombination) [3]. The most significant aspect of the HDDR process is that there is a dramatic change in the microstructure from an initial grain size of typically ~150 µm to a very fine, uniform grain size of about 0.1 - 0.3 µm [3-6]. On magnetisation, the HDDR nanocrystalline powder exhibits an appreciable coercivity and this means that, in its simplest net shape form, the powder can be mixed with a thermosetting resin to produce an isotropic and anisotropic permanent magnet by compression moulding [3-5].

Above-mentioned HDDR-process is based on hydrogen-induced reversible phase transformations in the RE-TM type hard magnetic alloys [6]. The transformation process is based on the formation of a RE-TM (rare-earth-transition-metal) hydride which at higher temperatures has a tendency to disproportionate into a mixture of RE-hydride and iron – direct hydrogen induced phase transformation that occurs in case of NdFeB-based alloys by the following scheme [6]

$$Nd_2Fe_{14}B \rightarrow NdH_2 + \alpha - Fe + Fe_2B$$
 (1)

Further, at second stage, subsequent desorption of the hydrogen using a vacuum ( $\sim 10^{-2}$  Torr) at high temperatures from decomposed alloy leads to recombination into initial phase of Nd<sub>2</sub>Fe<sub>14</sub>B – reverse hydrogen induced phase transformation by the following scheme in NdFeB-based alloys [6]

$$NdH_2 + \alpha - Fe + Fe_2B \rightarrow Nd_2Fe_{14}B$$
 (2)

The carrying out of these type phase transformations lead to formation of a fine-grained ferromagnetic phase  $Nd_2Fe_{14}B$  that allows to obtain permanent magnets with a high coercive [4,5].

Earlier the effect of the hydrogen pressure on the kinetics of hydrogen-induced direct phase transformations in RE-TM type alloys has been studied systematically in [7-10] and was established that phase transformation process accelerates as hydrogen pressure increase.

Thus, the main aim of this paper is to establish the influence of hydrogen pressure on kinetics of subsequent hydrogen-induced reverse phase transformations proceed by Equation (2) in the  $Nd_2Fe_{14}B$  type alloys and to describe kinetics features within a framework of classical kinetic theory of phase transformations in condensed state.

### 2. Experimental

Studies of the reverse phase transformations have been carried out on special hydrogen-vacuum equipment using a Sadikov's type magnetometer [9,10]. The industrial  $R_2$ Fe<sub>14</sub>B type alloy ( $R_{36.4}$ Fe<sub>62.45</sub>B<sub>1.15</sub>, where *R* is mixture of rare-earth metals – 33% Nd, 2% Pr, 0.9% Ce and 0.5% Dy, weight %) samples in the form of powder with average grain size ~100 µm (~1.25 g) were placed into the reaction chamber, which was evacuated to a pressure of ~1 Pa. Then, the samples were heated under vacuum to the desired temperature. After establishing isothermal conditions, the reaction chamber was filled with hydrogen under selected pressures ranging from 0.1 to 0.2 MPa. The direct transformation was continuously monitored under isothermal conditions by measuring the amount of newly formed ferromagnetic phases ( $\alpha$ -Fe and Fe<sub>2</sub>B)

according to scheme (1). After completion of the direct transformation, from moment of hydrogen evacuation from reaction chamber it lead to the reverse phase transformation evolution, *i.e.* recombination of decomposed phases into Nd<sub>2</sub>Fe<sub>14</sub>B phase according to scheme (2). The development of the reverse transformations was then followed by continuously monitoring the decreasing amount of the ferromagnetic phases in the sample. The resulting data were plotted as isothermal kinetic diagrams of the reverse transformations occurring in the  $R_2$ Fe<sub>14</sub>B compound.

### 3. Results and discussion

The isothermal kinetic diagrams of the reverse phase transformation in the industrial  $R_2$ Fe<sub>14</sub>B alloy at various temperatures and initial hydrogen pressures are shown in **Figure 1**. As follows from **Figure 1** if the reverse phase transformation starts from higher initial hydrogen pressure it leads to increase of phase transformation evolution for all transformation temperatures. In general, a



Figure 1. The isothermal kinetic diagrams for hydrogen induced reverse phase transformation in  $R_2$ Fe<sub>14</sub>B alloy, where *T* is the isothermal exposure temperature, *t* is the transformation time and 10, 30, 50, 70, 90 100% is the degrees of the reverse transformation at different initial hydrogen pressure: (a) – 0.10 MPa; (b) – 0.15 MPa; (c) – 0.20 MPa.

twofold increase of the initial hydrogen pressure (from 0.1 MPa up to 0.2 MPa) results in an acceleration of the reverse phase transformation evolution in the  $R_2$ Fe<sub>14</sub>B alloy in ~1.5–2 times.

As can be seen from Equation (2) for transformation of this type needs diffusion of alloy's components and in fact earlier on a base of kinetic, TEM and X-ray diffraction studies during reverse phase transformation in Nd<sub>2</sub>Fe<sub>14</sub>B type alloys has been showed that transformations of this type maybe classified as diffusive phase transformation in solid state and that the reverse transformation process proceeds by the nucleation and growth mechanism [11,12]. Because of this, according to detailed TEM investigations [12] at first NdH<sub>2</sub> phase dissociates into Nd due to desorption of  $H_2$  and then  $\alpha$ -Fe diffuses into Nd. The Fe<sub>2</sub>B grains act as boron carriers and due to their small size and random distribution there are short transfer-lengths for the boron atoms during recombination. Finally the disproportionated mixture recombines to the thermodynamically more stable Nd<sub>2</sub>Fe<sub>14</sub>B phase.

Therefore, it is obviously that from viewpoint of classical kinetic theory of phase transformations in condensed state above-described hydrogen-induced reverse phase transformation in Nd<sub>2</sub>Fe<sub>14</sub>B type alloys proceeds by the nucleation and growth mechanism. Further, it is possible to find an effective activation energy of phase transformation process in accordance with Becker-Döering model of nucleation kinetics [13,14] if plots dependence  $\ln t$  on 1/T where t is the time, which is needed for reaching of some degree of transformation and T is the transformation temperature. With this goal experimental data from Figure 1 were re-plotted in co-ordinates  $\ln t$  versus 1/T which are shown in Figure 2. The obtained values of effective energy of phase transformation for various hydrogen pressures and degrees of transformation are given in Tables 1.

As can be seen the from **Table 1** all obtained values of effective activation energy have good agreement by order of magnitude with activation energy for iron atoms diffusion in  $\alpha$ -phase of Fe ( $Q_{Fe}$ =259.54 ÷ 284.2 kJ/mol [15,16]). Therefore, it is really possible to consider that evolution process of reverse phase transformation is con-

trolled by iron atoms diffusion to new centres of  $Nd_2Fe_{14}B$  phase. On the other hand, it is obviously that the driving force of this transformation is dissociation of  $NdH_2$  phase due to desorption of  $H_2$ . Thus, in accordance with above-described model transformation let's obtain then kinetic equation for hydrogen induced reverse phase transformation in  $Nd_2Fe_{14}B$  type alloy taking into account influence of hydrogen pressure at direct phase transformation stage on reverse transformation kinetics.

In accordance with well known Kolmogorov kinetic theory of phase transformation in condensed state [17] the volume of transformed area during reverse phase transformation can be written as follows:

$$\xi = \frac{V(t)}{V_o} = 1 - \exp\left(-\frac{\pi}{3}I\omega^3 t^4\right),\tag{2}$$

where V(t) is the transformed area volume at time moment t,  $V_0$  is the initial untransformed volume, I is the nucleation rate of centres of new Nd<sub>2</sub>Fe<sub>14</sub>B phases, is the rate of growth of a new Nd<sub>2</sub>Fe<sub>14</sub>B phase.

On the other hand, rate of nucleation I of new Nd<sub>2</sub>Fe<sub>14</sub>B phases centers in condensed systems in accordance with Turnbull-Fisher model [18,19] in case of diffusion-controlled growth is

$$I = \gamma \frac{RT}{h} e^{-\frac{\Delta G + Q}{RT}},$$
(3)

where *G* is the energy necessary for formation of Nd<sub>2</sub>Fe<sub>14</sub>B critical nucleus, *Q* is the activation energy diffusion of Fe atoms to centres of new Nd<sub>2</sub>Fe<sub>14</sub>B phases,  $\gamma = 10^{-4} \text{ mol/m}^3$  [20], *R* is the gas constant, *h* is the Planck constant, *T* is transformation temperature.

Then, substitute equation (3) into (2) we can obtain kinetic equation for volume of the transformed area  $\xi$  in dependence on *t* transformation time and transformation temperature *T*:

$$\xi(t) = 1 - \exp\left(-\frac{\pi}{3}\gamma \frac{RT}{h}e^{-\frac{\Delta G + Q}{RT}}\omega^3 t^4\right)$$
(4)

As a rule, phase transformation kinetics for practical application describes by curves showing time transformation *t* needs for reaching some degree of transformation  $\xi$  in dependence on transformation temperature *T* 

Table 1. The effective activation energy of hydrogen induced reverse phase transformation in  $R_2$ Fe<sub>14</sub>B alloy for various initial hydrogen pressures *P* and degrees of phase transformation  $\xi$ .

$\xi$ , degree of transformation	P = 0.1 MPa, initial hydrogen pressure	P = 0.15 MPa, initial hydrogen pressure	P = 0.2 MPa, initial hydrogen pressure
0.5	$198.31 \pm 7.51 \text{ kJ/mol}$	181.24 ±6.78 kJ/mol	$214.23\pm8.05~kJ/mol$
0.7	$225.29\pm7.95~kJ/mol$	177.83 ± 7.96 kJ/mol	$216.62 \pm 8.23 \text{ kJ/mol}$
0.9	$224.46 \pm 8.14 \text{ kJ/mol}$	$224.99\pm7.96~kJ/mol$	$198.96 \pm 8.21 \text{ kJ/mol}$

1112 Growth Kinetics of Nd<sub>2</sub>Fe<sub>14</sub>B Phase During Hydrogen-Induced Reverse Phase Transformation in Nd<sub>2</sub>Fe<sub>14</sub>B Type Nanocrystalline Magnetic Alloy



Figure 2. The dependence of  $\ln t_{\xi}$  versus 1/T for hydrogen induced reverse phase transformation in  $R_2Fe_{14}B$  alloy for degrees of transformation -50% (a), 70% (b) and 90% (c) and following initial hydrogen pressure: 1 - 0.20 MPa; 2 - 0.15 MPa; 3 - 0.10 MPa. $\xi$ .

[22]. Thus, in this case Equation (4) has been written in following form:

$$t(\xi,T) = \left(\frac{3h}{\pi\gamma RT}\right)^{\frac{1}{4}} \frac{\left(-\ln(1-\xi)\right)^{\frac{1}{4}}}{\omega^{\frac{3}{4}}} e^{\frac{U}{4RT}}.$$
 (5)

Further, in isothermal conditions the rate of nucleation

*I* describing by Equation (3) is constant in accordance to classical theory of nucleation rate in condensed systems because W and Q as a rule are constants for same alloy [20,22]. Therefore, we can believe that the rate of nucleation of Nd<sub>2</sub>Fe<sub>14</sub>B phase is not depends on initial hydrogen pressure. Let's determine further rate of nucleation *I* and rate of growth of a new Nd<sub>2</sub>Fe<sub>14</sub>B phase  $\omega$ 

Copyright © 2011 SciRes.

Growth Kinetics of Nd<sub>2</sub>Fe<sub>14</sub>B Phase During Hydrogen-Induced Reverse Phase Transformation in Nd<sub>2</sub>Fe<sub>14</sub>B Type 1113 Nanocrystalline Magnetic Alloy

believed that the activation energy at transition of atoms through interface of phases Q is equal in our case to activation energy of diffusion of Fe atoms in  $\alpha$ -Fe phase Q= 259.54 kJ/mol [16] and energy necessary for formation of Nd<sub>2</sub>Fe<sub>14</sub>B critical nucleus  $\Delta G$  = 314.1 kJ/mol in accordance with data from [23]. Thus, using Equation (3) and kinetic data from **Figure 1** were calculated values of rate of nucleation *I* and rate of growth of Nd<sub>2</sub>Fe<sub>14</sub>B phase  $\omega$  during phase transformation for various hydrogen pressures and temperatures for degree of transformation  $\xi$  = 0.9 which are given in **Tables 2**.

In Figure 3 is presented dependence growth rate of  $Nd_2Fe_{14}B$  phase versus hydrogen pressures *P* plotted on the base of data from Table 2. As follows from Figure 3, the rate of growth  $\omega$  increase with increase of hydrogen pressure at all temperatures.

Further, in accordance with Lyubov and Hillert kinetic approach [20,21] for diffusion-controlled growth we assume that dependence rate of growth  $\omega$  on hydrogen pressure *P* and transformation temperature *T* can be approximated by following type function:

$$\omega = M \frac{\Delta F - \Delta F_s}{RT} e^{-\frac{U(P)}{RT}},$$

where *M* is proportional to the mobility coefficient of the interface of growing Nd<sub>2</sub>Fe<sub>14</sub>B phase,  $\Delta F$  is the molar difference of the free energies of initials and final phases,  $\Delta F_{\rm S}$  is the driving force of phase transformation which in our case is proportional to the dissociation energy of NdH<sub>2</sub> phase, U(P) is the activation energy transition of Fe atoms across the interface of Nd<sub>2</sub>Fe<sub>14</sub>B phase depending on hydrogen pressure.

Then, let's denote

$$M \frac{\Delta F - \Delta F_s}{RT} = A(P)$$

Further, activation energy transition of Fe atoms across interface of phases U(P) in dependence on initial hydrogen pressure P has been approximated using data from **Table 2** by following function:

$$U(P) = (113.08 \times 10^3 - 78.77 \times 10^3 \times P)$$

Finally, the rate of growth  $\omega$  depends on initial hydrogen pressure *P* in *R*<sub>2</sub>Fe<sub>14</sub>B alloy by following type equation:

$$\omega = A(P)e^{-\frac{113.08 \times 10^3 - 78.77 \times 10^3 \times P}{RT}},$$
(6)

where A(P) is the preexponential function that depends on hydrogen pressures P, which are presented in **Table 3** for various hydrogen pressure.

As can be seen from **Table 3**, A(P) function increase with increase of initial hydrogen pressure that is possible if the mobility coefficient of interface M will increase. In our case hydrogen atoms can be considered as interstitial atoms and increase of their concentration lead to increase of diffusion of matrix atoms (Fe, Nd, B atoms in our case) as was shown in [24-26]. Moreover, the hydrogen atoms concentration was larger in case if reverse transformation was started when hydrogen pressure was larger too and in this case it lead to increase of diffusion of matrix atoms and it correspondingly lead to increase of mobility of interface M. On the other hand, U(P) decrease with hydrogen pressure increase. Hence, the rate growth of new Nd<sub>2</sub>Fe<sub>14</sub>B phase  $\omega$  depends on two main factors: increasing of mobility coefficient of interface M with hydrogen pressure increase and decreasing of activation energy transition of Fe atoms through interface of  $Nd_2Fe_{14}B$  phase U(P) with hydrogen pressure increase. Finally, substitute Equation (6) into Equation (5) we can

written the final equation (6) into Equation (5) we can written the final equation descraibing dependence transformation time t needs for reaching some degree of transformation  $\xi$  on hydrogen pressures P and transformation temperature T:

$$t(\xi,T,P) = \left(\frac{3h}{\pi\gamma RT}\right)^{\frac{1}{4}} \frac{(-\ln(1-\xi))^{\frac{1}{4}}}{\left(A(P)e^{-\frac{113.08\times10^{3}-78.77\times10^{3}\times P}{RT}}\right)^{\frac{3}{4}}} e^{\frac{\Delta G+Q}{4RT}}, \quad (7)$$

Table 2. The rate of nucleation I and rate of growth of a new Nd<sub>2</sub>Fe<sub>14</sub>B phase  $\omega$  of phase transformation determined for various hydrogen pressures P and transformation temperatures T for degree of transformation  $\xi = 0.9$  in  $R_2$ Fe<sub>14</sub>B alloy.

T, temperature (K)	I, nucleation rate $(m^{-3} \cdot s^{-1})$	$\omega$ , rate of growth at $P = 0.1 \text{ MPa} (\text{m} \cdot \text{s}^{-1})$	$\omega$ , rate of growth at $P = 0.15 \text{ MPa} (\text{m} \cdot \text{s}^{-1})$	$\omega$ , rate of growth at $P = 0.2$ MPa (m·s <sup>-1</sup> )
983	0.392×10 <sup>3</sup>	3.448×10 <sup>-6</sup>	5.125×10 <sup>-6</sup>	6.064×10 <sup>-6</sup>
1003	1.623×10 <sup>3</sup>	4.336×10 <sup>-6</sup>	5.939×10 <sup>-6</sup>	7.114×10 <sup>-6</sup>
1023	6.357×10 <sup>3</sup>	8.895×10 <sup>-6</sup>	10.291×10 <sup>-6</sup>	12.42×10 <sup>-6</sup>



Figure 3. The growth rate of Nd<sub>2</sub>Fe<sub>14</sub>B phase  $\omega$  versus hydrogen pressure *P* for various transformation temperature: 1 - 710°C; 2 - 730°C; 3 - 750°C for degree of transformation  $\xi = 0.9$  in  $R_2$ Fe<sub>14</sub>B alloy.

Table 3. The preexponential function A(P) at different initial hydrogen pressures P determined for degree of reverse hydrogen induced transformation  $\xi = 0.9$  in  $R_2$ Fe<sub>14</sub>B alloy.

<i>P</i> , initial hydrogen pressure (MPa)	A(P), the preexponential function in Equation (6)
0.10	$94.73 \times 10^{-2}$
0.15	$97.41 \times 10^{-2}$
0.20	$98.76 \times 10^{-2}$

In **Figure 4** is shown the isothermal kinetic diagram for hydrogen induced reverse phase transformation in  $R_2$ Fe<sub>14</sub>B alloy calculated on the base of Equation (7) and data from **Table 3**.

Thus, it is possible to conclude that obtained Equation (7) well describes experimental results by influence of value of initial hydrogen pressure on kinetic of reverse phase transformation in  $R_2$ Fe<sub>14</sub>B alloy in terms of two main kinetic factors, *i.e.* increasing of mobility coefficient of interface M with hydrogen pressure increase and decreasing of activation energy transition of Fe atoms across interface of Nd<sub>2</sub>Fe<sub>14</sub>B phase U(P) with hydrogen pressure increase.

#### 4. Conclusions

The effect of initial hydrogen pressure on the kinetics of growth of Nd<sub>2</sub>Fe<sub>14</sub>B phase during hydrogen induced reverse phase transformations in the industrial  $R_2$ Fe<sub>14</sub>B alloy has been studied.

It has been established that, as the temperature and the initial hydrogen pressure increase it lead to considerable acceleration of evolution of reverse phase transformation. It has been obtained that kinetics of reverse phase transformation process is controlled by Fe atoms diffusion



Figure 4. The isothermal kinetic diagram for hydrogen induced reverse phase transformation in  $R_2$ Fe<sub>14</sub>B alloy calculated by Eq. (7) for degree of transformation  $\xi = 0.999$ for various hydrogen pressure: 1 – 0.10 MPa; 2 – 0.15 MPa; 3 – 0.20 MPa. Points are experimental data from Figure 1 for following hydrogen pressures.

and the rate growth of  $Nd_2Fe_{14}B$  phase  $\omega$  increase with increase of initial hydrogen pressure.

On the base of Kolmogorov kinetic theory of evolution of phase transformation in condensed state the equation describing the isothermal kinetic diagrams of such type of transformations has been obtained. It has been shown that effect of initial hydrogen pressure on kinetics of hydrogen induced reverse transformations in  $R_2$ Fe<sub>14</sub>B alloy the may be described by following type equation:

$$t(\xi,T,P) = \left(\frac{3h}{\pi\gamma RT}\right)^{\frac{1}{4}} \frac{\left(-\ln(1-\xi)\right)^{\frac{1}{4}}}{\left(\frac{A(P)e^{-\frac{113.08\times10^{3}-78.77\times10^{3}\times P}{RT}}\right)^{\frac{3}{4}}}e^{\frac{\Delta G+Q}{4RT}},$$

where  $t(\xi,T,P)$  is the transformation time for various degree of transformation  $\xi$  at different temperature *T* and initial hydrogen pressure *P*,  $\Delta G$  is the energy necessary for formation of Nd<sub>2</sub>Fe<sub>14</sub>B phase critical nucleus, *Q* is the activation energy diffusion of Fe atoms to centers of Nd<sub>2</sub>Fe<sub>14</sub>B phase,  $\gamma = 10^{-4}$  mol/m<sup>3</sup>, R is the gas constant, h is the Planck constant, *T* is transformation temperature, A(P) is the preexponential function depending on hydrogen pressure, *P* is the initial hydrogen pressure.

#### REFERENCES

[1] P. Campbell, "Permanent Magnet Materials and Their Applications," Cambridge University Press, Cambridge, 1994.

- [2] O. Gutfleisch, "Controlling the Properties of High Energy Density Permanent Magnetic Materials by Different Processing Routes," Journal of Physics D: Applied Physics, Vol. 33, No. 17, 2000, pp. R157-R172. doi:10.1088/0022-3727/33/17/201
- [3] A. Kirchner, W. Grunberger, O. Gutfleisch, V. Neu, K.-H. Muller and L. Schultz, "Textured NdFeB HDDR Magnets Produced by Die-Upsetting and Backward Extrusion," *Journal of Physics D: Applied Physics*, Vol. 31, No. 7, 1998, pp. 1660-1666. doi:10.1088/0022-3727/31/14/008
- [4] M. Liu, Y. Sun, G. B. Han, W. Yang and R. W. Gao, Dependence of Anisotropy and Coercivity on Microstructure in HDDR Nd–Fe–B Magnet," *Journal of Alloys* and Compounds, Vol. 478, 2009, pp. 303-307. doi:10.1016/j.jallcom.2008.12.048
- [5] S. Sugimoto, N. Koikea, D. Book, T. Kagotani, M. Okada, K. Inomata and M. Homma, "An Improved HDDR Treatment for the Production of Anisotropic Nd–Fe–B Ternary Powders," *Journal of Alloys and Compounds*, Vol. 330-332, 2002, pp. 892-896. doi:10.1016/S0925-8388(01)01503-1
- [6] T. Takeshita, "Present Status of the Hydrogenation-Decom-Position-Desorption-Recombination Process as Applied to the Production of Magnets," *Journal of Alloys and Compounds*, Vol. 193, 1993, pp. 231-234. doi:org/10.1016/0925-8388(93)90356-R
- [7] M. Kubis, K. H. Muller and L. Schultz, "Hydrogenation and Disproportionation of Sm2Fe17–xGax at High hydrogen Pressures," *Journal of Applied Physics*, Vol. 83, No. 11, 1998, pp. 6905-6907. <u>doi:10.1063/1.367589</u>
- [8] M. Kubis, A. Handstein, B. Gebel, O. Gutfleisch, K. H. Muller and L. Schultz, "Highly Coercive SmCO<sub>5</sub> Magnets Prepared by a Modified Hydrogenation-Disproportionation-Desorption-Recombination Process," *Journal of Applied Physics*, Vol. 85, No. 8, 1999, pp. 5666-5668. doi:10.1063/1.369834
- [9] V. A. Goltsov, S. B. Rybalka, A. F. Volkov, Y. G. Putilov and V. A. Didus, "Effect of Hydrogen Pressure on the Kinetics of the Hydrogen-Induced Diffusional Phase Transformation in an R<sub>2</sub>Fe<sub>14</sub>B Alloy," *The Physics of Metals and Metallography*, Vol. 89, No. 4, 2000, pp. 363-366.
- [10] V. A. Didus, S. B. Rybalka, D. Fruchart and V. A. Goltsov, "Influence of Hydrogen Pressure on the Kinetics of Hydrogen-Induced Diffusive Phase Transformations in the Nd<sub>2</sub>Fe<sub>14</sub>B Alloy," *Journal of Alloys and Compounds*, Vol. 356-357, 2003, pp. 386-389. doi:10.1016/S0925-8388(03)00224-X
- [11] S. B. Rybalka, V. A. Goltsov, V. A. Didus and D. Fruchart, "Fundamentals of the HDDR Treatment of Nd<sub>2</sub>Fe<sub>14</sub>B Type Alloys," *Journal of Alloys and Com-*

*pounds*, Vol. 356-357, 2003, pp. 390-394. doi:10.1016/S0925-8388(03)00362-1

- O. Gutfliesch, M. Matzinger, J. Fidler and I. R. Harris, "Characterisation of Solid-HDDR Processed Nd<sub>16</sub>Fe<sub>76</sub>B<sub>8</sub> Alloys by Means of Electron Microscopy," *Journal of*  Magnetism and Magnetic Materials, Vol. 147, No. 3, 1995, pp. 320-330. doi:10.1016/0304-8853(95)00026-7
- [13] R. Becker and W. Doering, "Kinetische Behandlung der Keimbildung in Uebersaetigen Daempfen," Annalen der Physik, Vol. 24, No. 8, 1935, pp. 712-752.
- [14] R. Becker, "Die Keimbildung bei der Ausscheidung In Metallischen Mischkristallen," *Annalen der Physik*, Vol. 32, No. 1, 1938, pp. 128-140. doi:10.1002/andp.19384240115
- [15] M. Lübbehusen and H. Mehrer, "Self-Diffusion in α-Iron: The Influence of Dislocation and the Effect of Magnetic Phase Transition," *Acta Metallurgica et Materialia*, Vol. 38, 1990, pp. 283-292. doi:10.1016/0956-7151(90)90058-O
- [16] S. D. Gertsriken and I. Ya. Dekhtyar, "Diffusion in Metals and Alloys in Solid Phase," GIFML, Moscow, 1960.
- [17] A. N. Kolmogorov, "On Statistical Theory of Metals Crystallization," DAN SSSR: Seriya Matematicheskaya, Vol. 1, No.1, 1937, pp. 355-360
- [18] S. Gleston, K. J. Laider and H. Eyring, "The Theory of Absolute Rate Processes," McGraw-Hill Book Company, New York, 1941.
- [19] D. Turnbull and J. C. Fisher, "Rate of Nucleation in Condensed Systems," *Journal of Chemical Physics*, Vol. 17, 1949, pp. 71-73. <u>doi:10.1063/1.1747055</u>
- [20] B. Ya. Lyubov, "Kinetic Theory of Phase Transformations," Metallurgiya, Moscow, 1969.
- [21] M. Hillert, "Diffusion and Interface Control of Reactions in Alloys," *Metallurgical Transactions A*, Vol. 6A, 1975, pp. 5-19. <u>doi:10.1007/BF02673664</u>
- [22] J. W. Christian, "The Theory Transformations in Metals and Alloys," Pergamon Press, Oxford, 2002.
- [23] S. B. Rybalka, "Kinetics of Hydrogen-Induced Diffusive phase Transformations in Nd<sub>15</sub>Fe<sub>77</sub>B<sub>8</sub> Alloy," *Bulletin of Donetsk University A*, No. 1, 2002, pp. 286-290.
- [24] P. L. Gruzin, Yu. V. Korneev and G. V. Kurdyumov, "Effect of Carbon on Self-Diffusion of Iron," *DAN SSSR: Seriya Tekhnicheskoy Phisiki*, Vol. 80, No.1, 1951, pp. 49-51.
- [25] H. W. Mead and C. E. Birchenall, "Self-Diffusion of Iron in Austenite," *Journal of Metals*, Vol. 8, No. 10, 1956, pp. 1336-1339.
- [26] A. A. Smirnov, "The Molecular-Kinetic Theory of Metals," Nauka, Moscow, 1966.